


SCUBAPOXY 5335

Flexible Underwater-applied Sealant



Case History



PROJECT SUMMARY

Client	Swimming Centre
Location	Western Australia
Colour	Standard (Mid-grey)
Area	Unknown
Installer	Fremantle Commercial Diving



COMMENTS

- A 50-metre pool in a swimming centre needed some extensive maintenance work after a survey conducted by a professional diving company. In addition to major expansion joint repairs, the survey also identified a number of tiles that were damaged or loose and needed to be replaced.
- Five tiles were replaced and re-grouted using Scubapoxy 5335 as part of the original scope of works, which included 4 white biscuit tiles and one black lane marker tile. In addition to those, several other tiles were identified as needing replacement while work was being carried out - some in a junction box in the deeper end, and others on a section of backing tiles located near the diving platform.
- The resulting repairs achieved a good result aesthetically, were solid, and solved a few OH&S issues in the process.