
RESIN GRANITE™

Decorative Flake Flooring System



Case History



COMMENTS

- Homeowners Gavin and Kirsty were looking for an attractive and practical flooring solution for the new 68m² shed they had erected in their backyard.
- While it appeared to be a straightforward project on the surface, there were a number of challenges that presented during installation. This included a hard concrete slab that was difficult to grind and prepare thoroughly, as well as consistently wet weather throughout the installation period.
- Despite these challenges, both owners were extremely pleased with the end result and were looking forward to making full use of their upgraded asset.